



GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program May 9, 2013

Reviewed: 

Mine Name: Rockland Mine (Body Tody)	Permit Number: M/015/0040
Operator Name: Miracle Rock Mining and Research	Inspection Date: May 8, 2013
Inspector(s): Wayne Western	Time:
Other Participants:	Mine Status: ACT
Weather Condition: cool and overcast skies	Last Inspection: June 27, 2012
Bond Renewal Date: June 24, 2014	Bond Amount: \$130,428.00
Surface Ownership: Sitla	Mineral Ownership: Sitla
Last Year of Production: NA	Acreage: 7 Acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The bond was escalated to 2013. The Permittee should provide updated bond calculations.

Annual fees were paid.

No water appeared to flow off site. There were areas of standing water.

Inspection Date: May 8, 2013

Page 2 of 4


M/015/0040

Conclusions and Recommendations:

The Permittee should update the bond calculations and provide the Division with an annual report for 2013.

Directions to Site:

Inspector's Signature

A handwritten signature in cursive script, appearing to read "Wayne White", is written over a horizontal line.

WHW:

cc: (OPERATOR)

John Blake, SITLA

O:\M015-Emery\M0150040-MiracleRock\inspection\Insp-05082013.doc



Fuel tank



Mine building



Pit



Pit and overburden